

# The Investigation of Stability on Slopes Utilizing Reinforcement Gabion Walls and Concrete Piles for Mitigating Landslide Disasters



Banta Chairullah<sup>1</sup>, Munira Sungkar<sup>1</sup>, Reza Pahlevi Munirwan<sup>1,\*</sup>, Khaizal Jamaluddin<sup>1</sup>, Ferda Febrian Ramadhani<sup>1</sup> and Ramadhansyah Putra Jaya<sup>2</sup>

<sup>1</sup>Department of Civil Engineering, Faculty of Engineering, Universitas Syiah Kuala, Jln. Tgk. Syech Abdurrauf, No. 7, Darussalam, Banda Aceh 23111, Indonesia

<sup>2</sup>Faculty of Civil Engineering Technology, Universiti Malaysia Pahang Al-Sultan Abdullah, Kuantan 26300, Pahang, Malaysia

## Abstract:

**Introduction:** Landslides frequently occur along roads crossing mountainous terrain during the rainy season, posing a significant risk of severe disruption to land transportation routes. Efficient and accurate resolutions are essential in managing landslides to facilitate immediate transportation recovery, such as gabion walls and pile installation.

**Aim:** This article aimed to evaluate the effect of installing gabions and piles for safety measures on the stability of slope landslides. The analysis of slope stability was performed utilizing the Plaxis 2D software. For reinforced slopes, the Safety Factor (SF) value utilized as a benchmark for evaluating slope stability was  $SF \geq 1.5$ .

**Methods:** An assessment of the stability of the slope was conducted under three conditions: its original state, after reinforcement with gabions, and after the integration of gabions with mini piles. The dimensions of the gabion setting, as determined by the L-W-H notation (length-width- height), were 2 m x 1 m x 0.5 m and 1 m x 2 m x 0.5 m. The pile was designed to be 2.5 m long at the gabion's end. The analysis was conducted at 45°, 60°, 70°, and 90° slopes.

**Results:** Based on the results of slope stability calculations, an  $SF = 1.11$  was determined under no reinforcement conditions. By applying reinforced gabion walls measuring 2 m in width combined with mini piles at a 45° slope, the best SF was achieved, which was 2.58.

**Conclusion:** Given the comparable topographical circumstances, it is expected that the outcomes of this analysis on slope stability will be applicable in mitigating the occurrence of landslides.

**Keywords:** Gabion, Landslide, Mini pile, Safety factor, Slope stability, Concrete piles.

© 2024 The Author(s). Published by Bentham Open.

This is an open access article distributed under the terms of the Creative Commons Attribution 4.0 International Public License (CC-BY 4.0), a copy of which is available at: <https://creativecommons.org/licenses/by/4.0/legalcode>. This license permits unrestricted use, distribution, and reproduction in any medium, provided the original author and source are credited.



Received: February 13, 2024

Revised: May 13, 2024

Accepted: May 29, 2024

Published: ?? ??, 2024

\*Address correspondence to this author at the Department of Civil Engineering, Faculty of Engineering, Universitas Syiah Kuala, Jln. Tgk. Syech Abdurrauf, No. 7, Darussalam, Banda Aceh, Indonesia, 23111; E-mail: r.munirwan@usk.ac.id

Cite as: Chairullah B, Sungkar M, Munirwan R, Jamaluddin K, Ramadhani F, Jaya R. The Investigation of Stability on Slopes Utilizing Reinforcement Gabion Walls and Concrete Piles for Mitigating Landslide Disasters. , 2024; 18: e18748368310059. <http://dx.doi.org/10.2174/0118748368310059240605115115>



Send Orders for Reprints to [reprints@benthamscience.net](mailto:reprints@benthamscience.net)

## 1. INTRODUCTION

The movement of soil or rock from one location to another in a vertical, horizontal, or sloping direction is known as a landslide. Landslides have the potential to be

classified as natural disasters and they can be caused by two primary sources: natural factors and trigger events [1-3]. Natural factors, such as the topography or slope of the ground, the hydrological conditions or water content in the soil, and the structure and strength of the



## 2. MATERIALS AND METHODS

The investigation was conducted at the location of Bireuen-Takengon Road, particularly in Jamur Ujung Village, Wih Pesam District, Bener Meriah Regency, Aceh Province. The research location is situated at the geographical coordinates of 4°42'24.08" N and 96°49'15.59" E. Additionally, it is located at an elevation of 1.227 meters above the sea level. The study encompassed the setting up of a field survey, laboratory experimentation, and software analysis. The field survey was carried out through the collection of soil samples and the use of GPS technology. The main quantitative data were acquired by laboratory investigation of soil samples to ascertain the material properties and input specifications for software analysis. Secondary data were obtained by performing a literature review and interacting with the local community.

There were two types of samples used in sampling: undisturbed and disturbed. Undisturbed samples of unsaturated soil conditions were collected by the test pit method. This method involves collecting samples using metal tubes at depths of 2 m and 5 m. This is because visual observation indicates that the soil layer between 1 and 4 meters has a similar soil type, as does the layer between 5 and 6 meters. Therefore, there are two distinct soil layers. To ensure consistency, both sides of the tube are coated with wax. This is done to maintain the soil's water content until the test is conducted. Disrupted samples of unsaturated soil conditions were also collected at depths of 2 m and 5 m and promptly placed into soil sacks. The collected data served as input for slope stability analysis with the Plaxis 8.6 version. Table 1 shows the soil parameters used in this study.

The soil parameters were utilized as input data to derive various calculation outcomes for reinforcing retaining walls along the research area. Soil volume

weight ( $\gamma$ ), cohesiveness ( $c$ ), and angle of friction in the soil ( $\phi$ ) were the data utilized for slope stability analysis using Plaxis. These values were derived from laboratory test results on soil samples at the study site. Additionally, relevant data, such as the dilatancy angle ( $\Psi$ ), Poisson's ratio ( $\nu$ ), soil permeability coefficient ( $k_x$ ,  $k_y$ ), and soil elastic modulus ( $E$ ) were sourced from the available literature, specifically based on laboratory test results corresponding to the particular soil type. Several analysis variables were determined and entered into the Plaxis program to generate the slope geometric model applied to stability analysis. The inspection of slope stability was conducted under two conditions: the original state and the strengthened state, as can be seen in Fig. (2). The original state involved inputting the initial geometric conditions before slope collapse, derived from empirical data. Adding gabion reinforcement and a combination of gabions and concrete minipiles at the base of the slope constituted the strengthening condition.

Additionally, the study examined slope stability reinforcement through the analysis of three scenarios: without the use of retaining walls, with the use of retaining gabion walls, and with the use of gabion walls in combination with concrete minipiles. The construction of gabion walls with a combination of concrete minipiles was planned based on the considerations specified in Table 2. Before determining the proper position of the gabion walls for soil retention, it is essential to evaluate the extent of the landslide area on the slope. The location of the soil-retaining gabion wall, in conjunction with the positioning of concrete minipiles, may affect the Safety Factor (SF) of the slope. If the SF satisfies the minimum criteria, the option of utilizing a soil-retaining gabion wall combined with minipiles becomes feasible for installation. If multiple positions fulfill the slope stability safety factor requirements, the placement that is most efficient and cost-effective is preferred.

**Table 1. Soil Parameters at the site of the study.**

Soil Parameter	Layer 1	Layer 2	Backfill Material	Gabion	Unit
	Sandy Silt	Clayey Silt	Clayey Sand		
AASHTO classification	A-4	A-4	A-7	-	-
USCS classification	ML	OL	MH	-	-
Type of behavior	Drained	Drained	Drained	Drained	-
Dry soil weight ( $\gamma_{dry}$ )	11.164	10.438	12.625	25.000	kN/m <sup>3</sup>
Wet soil weight ( $\gamma_{wet}$ )	16.363	16.245	16.873	26.672	kN/m <sup>3</sup>
Horizontal permeability ( $k_x$ )	0.0864	0.00864	0.0864	86.4	m/day
Vertical permeability ( $k_y$ )	0.0864	0.00864	0.0864	86.4	m/day
Young's modulus ( $E_{soil}$ )	9,810	19,620	29,430	1,373,400	kN/m <sup>2</sup>
Poisson's ratio ( $\nu$ )	0.3	0.3	0.3	0.4	-
Cohesion ( $c$ )	7.85	8.83	34.34	17.7	kN/m <sup>2</sup>
Friction angle ( $\phi$ )	33.3	35.7	25.8	45	°
Dilatancy angle ( $\Psi$ )	3.3	5.7	0	15	°




Fig. (2). Scenarios of gabion wall and minipile design for slope reinforcement.


Table 2. Experimental variables.

No.	Variable	Remarks
1.	Gabions dimension	Dimension 2m x 1m x 0.5m (length x width x height)
		Dimension 1m x 2m x 0.5m (length x width x height)
2.	Slope angle	45°
		60°
		70°
		90°
3.	Minipile dimension	Diameter = 0.2 m Length = 2.5 m


**3. RESULTS AND DISCUSSION**

Field observations from several viewpoints indicated the landslide to be of the rotating type, characterized by the movement of soil and rock masses along a concave-shaped sliding plane. The research input from the Plaxis analysis, depicted in Fig. (3), revealed the geometry of the landslide area to closely resemble the patterns observed in the field. Based on the results, the SF for an unreinforced slope was 1.11, indicating an unstable slope. Furthermore, Fig. (4) displays the results of the Plaxis analysis, specifically the slope with reinforcement of gabions and concrete minipiles.

Table 3 displays the quantitative effects of the gabion arrangement as well as the combined effect of gabions with concrete minipiles on the slope safety factor. The computation of the slope safety factor revealed the SF in the no-reinforcement state to be  $SF = 1.11$ , indicating landslide events aligning with the actual conditions on the site. Furthermore, the slope model with reinforcement yielded SF calculation results that all exceeded 1.5, indicating stable slope conditions. This condition was present on slopes that had reinforcement at all angles, except for slopes with a 90-degree angle when the SF was less than 1.5.



**Fig. (3).** Unreinforced slope results from the plaxis analysis.



*Fig. 6 contd.....*




Fig. (4). Slope results with reinforcement of gabions and concrete minipiles from the plaxis analysis.

**Table 3.** The safety factor of the slope with gabion walls and minipile reinforcement.

No.	Gabion Dimension L x W x H	Minipile	Safety Factor			
			Slope Angle			
			45°	60°	70°	90°
1	2x1x0.5 m	With minipile	2.24	1.89	1.73	1.26
2	1x2x0.5 m	With minipile	2.58	2.23	1.91	1.46
3	2x1x0.5 m	No minipile	2.20	1.79	1.53	1.18
4	1x2x0.5 m	No minipile	2.57	2.21	1.88	1.31


**Fig. (5).** Relationship among the gabion, minipiles, and the safety factor.

Fig. (5) plots the findings of the analysis related to the effects of concrete minipiles on the combination model incorporating gabions. The results indicated that the utilization of minipiles affected the safety factor of the slope. In contrast to the strengthening model that solely employed gabions, enhancing the safety factor of the slope with concrete minipiles was possible when gabions were utilized in conjunction with minipiles. Additionally, as the angle of the slope decreased, the safety factor increased, specifically  $SF > 1.5$ . Conversely, an increase in slope angle resulted in a corresponding reduction in the slope's safety factor ( $SF < 1.5$ ), indicating the slope to no longer be secure even at a 90-degree angle.

In addition, as presented in Fig. (5), the study determined the influence of the slope angle on the slope safety factor. A decrease in the slope angle led to an increase in the safety factor. Conversely, when the slope angle increased, the safety factor decreased. At a slope angle of 90 degrees, the slope safety factor was less than

1.5, indicating the slope to no longer be safe. Additionally, combining gabions with concrete minipiles could enhance the safety factor of the slope above the strengthening procedure that only relied on gabions. The analytical results indicated that the gabion arrangement with dimensions of L-W-H (1x2x0.5) m presented a higher safety factor in comparison to the L-W-H (2x1x0.5) m model. This demonstrated that a gabion with a wider width was capable of withstanding larger external forces. Horizontal (lateral) force is one of the movements that occur in landslides. Hence, by increasing the width (W dimension) of the gabion, the length of the shear plane between the gabion's base and the ground may also grow. Consequently, the shear force that opposes the lateral movement would be greater, thus enhancing the slope safety factor. Based on the assessment results of an increase in slope SF, it can be inferred that the variables of the L-W-H gabion arrangement model had a greater influence on enhancing SF compared to the influence of

the minipile combination model. The effect of the gabion arrangement resulted in a significant increase in the safety factor, compared to the improvement obtained with the combination of concrete minipiles. The analysis revealed that the gabion arrangement model variables exhibited greater effectiveness compared to the minipile combination model variables. The potential shape of the slope failure line in the analytical slope model was believed to have minimal effect on the increase of the safety factor for slope stability.

## CONCLUSION

According to the results of the slope stability investigation conducted at the site of the landslide study, the following assumptions were made:

- The landslide that occurred in the research area was of the rotational type. In addition, the determined safety factor for the no-reinforcement conditions was 1.11, indicating the landslides to frequently occur in the region.
- The use of reinforcement through a gabion structure and a combination structure consisting of a concrete minipile could increase the safety factor across all slope angles, up to 70 degrees. Hence, to perform reinforcement using gabions, it was essential to restrict the inclination of the slope to a maximum of 70 degrees.
- The analytical results indicated the inclination of the slope to have a significant impact on its stability. That is, the lower the slope angle (sloping), the safer the slope. In all strengthening model settings, when the slope angle was 90°, the SF was less than 1.5, indicating that it failed to meet the slope safety standards.
- The model with gabion reinforcement with concrete minipiles and a 45-degree slope measuring length (L) x width (W) x height (H) = 1x2x0.5 m yielded the highest safety factor, *i.e.*, 2.58.
- The study also showed the variables in the L-W-H gabion arrangement model to have a greater effect on increasing the slope safety factor than the variables in the concrete minipile combination model. This demonstrated the variables of the gabion arrangement model to be more efficient than the variables of the concrete minipile combination model.
- Additional information on the geological and hydrological characteristics of the region, the economic feasibility and construction challenges associated with implementing gabion walls and minipiles in real-world scenarios, as well as the long-term performance and durability of the proposed reinforcement methods, should be taken into consideration in the future to make the analysis more comprehensive.

## AUTHORS' CONTRIBUTION

It is hereby acknowledged that all authors have accepted responsibility for the manuscript's content and consented to its submission. They have meticulously reviewed all results and unanimously approved the final version of the manuscript.

## ABBREVIATION

SF = Safety Factor

## CONSENT FOR PUBLICATION

Not applicable.

## AVAILABILITY OF DATA AND MATERIALS

The data and supportive information are available within the article.

## FUNDING

None.

## CONFLICT OF INTEREST

The authors declare no conflict of interest, financial or otherwise.

## ACKNOWLEDGEMENTS

The authors acknowledge the support provided by the Universitas Syiah Kuala, Banda Aceh, Indonesia. In addition, the authors are grateful to the Soil Mechanics Universitas Syiah Kuala's laboratory staff for supporting the experimentation and data collection.

## REFERENCES

- [1] G. De Santis, N. Egidi, J. Giacomini, E. Gioia, P. Maponi, and L. Spadoni, "Landslide Hazard Assessment Model for Slope Stability Analysis", *JAACM*, vol. 10, pp. 77-87, 2023. [<http://dx.doi.org/10.15377/2409-5761.2023.10.8>]
- [2] H. Ding, H. Zhang, B. Liu, and H. Huang, "Study on mechanical properties of soil stabilization by different vegetation roots on high steep slope", *Sustainability*, vol. 15, no. 3, p. 2569, 2023. [<http://dx.doi.org/10.3390/su15032569>]
- [3] N. Antonaki, T. Abdoun, and I. Sasanakul, "Centrifuge tests on liquefaction potential and slope stability of mine tailings", *IJPMG*, vol. 19, no. 2, pp. 104-114, 2019. [<http://dx.doi.org/10.1680/jphmg.17.00068>]
- [4] A. Masoodi, M.R. Majdzadeh Tabatabai, A. Noorzad, and A. Samadi, "Riverbank stability under the influence of soil dispersion phenomenon", *J. Hydrol. Eng.*, vol. 24, no. 3, p. 05019001, 2019. [[http://dx.doi.org/10.1061/\(ASCE\)HE.1943-5584.0001756](http://dx.doi.org/10.1061/(ASCE)HE.1943-5584.0001756)]
- [5] Z. Dai, J. Guo, H. Luo, J. Li, and S. Chen, "Strength characteristics and slope stability analysis of expansive soil with filled fissures", *Appl. Sci.*, vol. 10, no. 13, p. 4616, 2020. [<http://dx.doi.org/10.3390/app10134616>]
- [6] H. Hafiz, F. A. Kechik, A. Ibrahim, A. M. Taib, and D. Z. A. Hasbollah, "Investigation of unsaturated soil hydraulic properties for subgrade improvement using marble dust waste", *Open Constr. Build. Technol. J.*, vol. 18, no. 1, pp. 1-12, 2024. [<http://dx.doi.org/10.2174/0118748368296535240305065924>]
- [7] S.K. Chen, and X. Zhang, "Seepage control in a high concrete face-rock fill dam based on the node virtual flow method", *Open Constr. Build. Technol. J.*, vol. 10, no. 1, pp. 547-560, 2016. [<http://dx.doi.org/10.2174/1874836801610010547>]
- [8] T. Cao, H. Zhang, T. Chen, C. Yang, J. Wang, Z. Guo, and X. Sun, "Research on the mechanism of plant root protection for soil slope stability", *PLoS One*, vol. 18, no. 11, p. e0293661, 2023. [<http://dx.doi.org/10.1371/journal.pone.0293661>] [PMID: 38011254]
- [9] A.N.C. Ghani, A.M. Taib, and D.Z.A. Hasbollah, "Effect of rainfall pattern on slope stability", *Lect. Notes Civil Eng.*, vol. 62, no. January, pp. 887-892, 2020. [[http://dx.doi.org/10.1007/978-981-15-2184-3\\_115](http://dx.doi.org/10.1007/978-981-15-2184-3_115)]
- [10] F.A. Kechik, A. Ibrahim, Z. Abu Hassan, S.J. Matlan, A.M. Taib,



- and N.A. Rahman, "Analysis of influence of air-entry values to unsaturated soil properties", In: *Phys. Chem. Earth.*, vol. 129, 2023, p. 103340.  
[<http://dx.doi.org/10.1016/j.pce.2022.103340>]
- [11] J. Xu, and X. Yang, "Effects of seismic force and pore water pressure on three dimensional slope stability in nonhomogeneous and anisotropic soil", *KSCE J. Civ. Eng.*, vol. 22, no. 5, pp. 1720-1729, 2018.  
[<http://dx.doi.org/10.1007/s12205-017-1958-y>]
- [12] R.P. Munirwan, M.R. Taha, A. Mohd Taib, and M. Munirwansyah, "Shear strength improvement of clay soil stabilized by coffee husk ash", *Appl. Sci.*, vol. 12, no. 11, p. 5542, 2022.  
[<http://dx.doi.org/10.3390/app12115542>]
- [13] X. Xu, L. Shao, J. Huang, X. Xu, D. Liu, Z. Xian, and W. Jian, "Effect of wet-dry cycles on shear strength of residual soil", *Soil Found.*, vol. 61, no. 3, pp. 782-797, 2021.  
[<http://dx.doi.org/10.1016/j.sandf.2021.03.001>]
- [14] B.G. Habtemariam, K.B. Shirago, and D.D. Dirate, "Effects of soil properties and slope angle on deformation and stability of cut slopes", *Adv. Civ. Eng.*, vol. 2022, pp. 1-10, 2022.  
[<http://dx.doi.org/10.1155/2022/4882095>]
- [15] L. Meko, Y.C. Chemedda, and B. Meko, "Road cut slope stability analysis for static and dynamic (pseudo-static analysis) loading conditions", *Open Geosci.*, vol. 15, no. 1, p. 20220561, 2023.  
[<http://dx.doi.org/10.1515/geo-2022-0561>]
- [16] T.T. Woldesenbet, H.B. Arefaine, and M.B. Yesuf, "Numerical stability analysis and geotechnical investigation of landslide prone area (the case of Gechi district, Western Ethiopia)", *Environmental Challenges*, vol. 13, p. 100762, 2023.  
[<http://dx.doi.org/10.1016/j.envc.2023.100762>]
- [17] M. Gharehdaghi, H.S. Tehrani, and A. Fakher, "Risk-based decision making method for selecting slope stabilization system in an abandoned open-pit mine", *Open Constr. Build. Technol. J.*, vol. 14, no. 1, pp. 198-217, 2020.  
[<http://dx.doi.org/10.2174/1874836802014010198>]
- [18] M.I.N. Mohamed Azam, M.F. Yusof, and M.K. Abu Talib, "Plaxis 2D modelling of an anchor sheet pile for soil slope strengthening at Segamat, Johor", *JSUE*, vol. 3, no. 2, 2023.  
[<http://dx.doi.org/10.30880/jsue.2023.03.02.005>]
- [19] N.K. Kokutse, A.G.T. Temgoua, and Z. Kavazović, "Slope stability and vegetation: Conceptual and numerical investigation of mechanical effects", *Ecol. Eng.*, vol. 86, pp. 146-153, 2016.  
[<http://dx.doi.org/10.1016/j.ecoleng.2015.11.005>]
- [20] T. Joyraj Singh, and M. Pradipchandra Singh, "Inuence of plant roots on slope stabilization: A geotechnical investigation", *Res Seq*, 2021.  
[<http://dx.doi.org/10.21203/rs.3.rs-623966/v1>]
- [21] E. B. Masi, S. Segoni, and V. Tofani, "Root reinforcement in slope stability models: A review", *Geosciences*, vol. 11, no. 5, 2021.  
[<http://dx.doi.org/10.3390/geosciences11050212>]
- [22] F. Ayalneh Mekonnen, "Performance evaluation of geometric modification on the stability of road cut slope using FE based plaxis software", In: *Landslides*, IntechOpen, 2022.  
[<http://dx.doi.org/10.5772/intechopen.99633>]
- [23] I.H. Razali, A. Mohd Taib, N. Abd Rahman, D.Z. Abang Hasbollah, M.F. Md Dan, A.B. Ramli, and A. Ibrahim, "Slope stability analysis of riverbank in Malaysia with the effects of vegetation", *Phys. Chem. Earth Parts ABC*, vol. 129, no. December, p. 103334, 2023.  
[<http://dx.doi.org/10.1016/j.pce.2022.103334>]
- [24] B. Bin Xu, and W. Si, "Influence of strength parameters of soil on the slope stability", *MATEC Web Conf.*, vol. 63, p. 02032, 2016.
- [25] F. Kassou, J.B. Bouziyane, A. Ghafiri, and A. Sabihi, "Slope stability of embankments on soft soil improved with vertical drains", *Civ. Eng. J.*, vol. 6, no. 1, pp. 164-173, 2020.  
[<http://dx.doi.org/10.28991/cej-2020-03091461>]
- [26] A.N. El-Hazek, N.B. Abdel-Mageed, and M.H. Hadid, "Numerical and experimental modelling of slope stability and seepage water of earthfill dam", *J. Water Land Dev.*, vol. 44, pp. 55-64, 2019.  
[<http://dx.doi.org/10.24425/jwd.2019.127046>]
- [27] B.M. Das, *Advanced soil mechanics.*, 3rd ed Taylor & Francis: New York, 2008.
- [28] M. Munirwansyah, "Geotechnical approach for occupational safety risk analysis of critical slope in open pit mining as implication for earthquake hazard", *IOP Conf Ser Mater Sci Eng*, vol. 352, p. 012035, 2018.  
[<http://dx.doi.org/10.1088/1757-899X/352/1/012035>]
- [29] M. Sungkar, M. Munirwansyah, R.P. Munirwan, and D. Safrina, "Slope stability analysis using bishop and finite element methods", *IOP Conf. Ser.: Mater. Sci. Eng.*, vol. 933, p. 012035, 2020.  
[<http://dx.doi.org/10.1088/1757-899X/933/1/012035>]
- [30] Y.O. Özkılıç, M. Karalar, C. Aksoylu, A.N. Beskopylny, S.A. Stel'makh, E.M. Shcherban, S. Qaidi, I.S.A. Pereira, S.N. Monteiro, and A.R.G. Azevedo, "Shear performance of reinforced expansive concrete beams utilizing aluminium waste", *J. Mater. Res. Technol.*, vol. 24, pp. 5433-5448, 2023.  
[<http://dx.doi.org/10.1016/j.jmrt.2023.04.120>]
- [31] I.P. Hastuty, and R. Prambudi, "Analysis of slope stability by the planning of cantilever retaining wall reinforcement using the application of Plaxis (case study: Substation Panyabungan sta 0+060)", *IOP Conf. Ser.: Mater. Sci. Eng.*, vol. 851, p. 012021, 2020.  
[<http://dx.doi.org/10.1088/1757-899X/851/1/012021>]
- [32] S. Ghosh, "Formulation of seismic passive resistance of retaining wall backfilled with c-F soil", *Int. J. Geotech. Earthq. Eng.*, vol. 3, no. 2, pp. 15-24, 2012.  
[<http://dx.doi.org/10.4018/jgee.2012070102>]
- [33] A. Saeed, H.M. Najm, A. Hassan, S. Qaidi, M.M.S. Sabri, and N.S. Mashaan, "A comprehensive study on the effect of regular and staggered openings on the seismic performance of shear walls", *Buildings*, vol. 12, no. 9, p. 1293, 2022.  
[<http://dx.doi.org/10.3390/buildings12091293>]
- [34] H. Asadpour, and T. Akhlaghi, "Stability analysis of gabion wall with tieback in seismic regions", *Civ. Eng. J.*, vol. 3, no. 5, pp. 319-331, 2017.
- [35] J. Nazrien Ng, "The effect of extreme rainfall events on riverbank slope behaviour", *Front. Environ. Sci.*, vol. 10, no. March, pp. 1-14, 2022.  
[<http://dx.doi.org/10.3389/fenvs.2022.859427>]